

Figure 1




Figure 2

T (°C)	H (Relative Humidity)	Reject C <sub>Ri</sub> if C <sub>Ri</sub>
< 0	any humidity	> C <sub>3</sub>
>0	>80%	< C <sub>3</sub>

Figure 3A

Corrosivity Ratio (%)	Recommended Postponement (days)
< 20	0
20 - 40	30
40 - 60	60
> 60	90

Figure 3B